



Sites 6, 16, 24 are dominated by bedrock outcropping which are always ranked as a one

Site 18 was bedrock dominated, site 25 had a large beaver dam at transect A that pooled to transect D. Site XY was at the McLeod Trailhead and exhibited both natural old growth log jams and restoration projects



Prepared by Demeter Design for the Siuslaw Watershed

- North Fork Siuslaw Watershed Bank Condition
- No Disturbance on Banks
 - Low
 - Medium
 - medium high
 - high
 - ★ human low
 - ★ human medium
 - ★ human medium high
 - ★ human high
 - North_Fork_Siuslaw_5th_Field
 - No Listing
 - Listing



Map 7 - Alternate Measure of Bank Condition